



## Blender Socket, Replacement for Vita-Mix #015546

Our drive socket will replace Vita-Mix part number 891 and 802. The drive socket should work correctly on the following Vita-Mix Models: 1002, 1230, 5006, 5012, 5057, BarBoss, 5039, VITA-MIX, VM0100, VM0100A, Total Nutrition Centers, Vita-Prep, Drink Machine Models. Customers have purchased and installed our drive sockets on Vita-Mix models 5000 and 5200, the type of blenders being sold for home use at stores like Costco. Based on this information, our socket should work correctly on these models, 5000 and 5200.

[Read More](#)

**SKU:** 0015546

**Price:** \$8.65

**Categories:** [Vita-Mix](#)

### Product Description

---



## Foot, Pack of 4 Replacement #000794

Fits Models 1230, 136053, 5006, 5012, Blend Station Adv C Counter, Drink Machine Timer, Drink Machine Sec Timer, Drink Machine Speed, T&G 2 On-C Vita Prep, Vita-Prep

[Read More](#)

**SKU:** 000794

**Price:** \$4.14

**Categories:** [Vita-Mix](#)

**Product Description**

Foot, Pack Of 4 Pieces

---